













DESCRIPTION : L-13 Dust Cap-seal	PART WEIGHT 9 Grams
---	-------------------------------

EMBOSSMENTS		INSTALLATION INSTRUCTIONS	
Part Name	Cavity Number	Step 1: Insure that cap-seal has be inspected and is in good condition.	Step 2: Inspect L-13 bead on drum to
			
			

SEPCIFICATION DRAWING	
 <p>CONTINUOUS TEAR STRIP</p> <p>1/8 DIA. THRU</p> <p>9/32</p> <p>1/4</p> <p>Optional Hot Stamping</p> <p>TOP VIEW</p> <p>11/32</p> <p>ø3.25±.01</p> <p>ø3.05±.01</p> <p>3/32</p>	<p>Step 3: Align the pull tab with the parting line.</p>  <p>Step 4: Using thumbs, push around the edge of the L-13 cap-seal until it snaps on.</p>  <p>Step 4: Inspect the L-13 Cap-seal to insure the it has snapped completely under the L-13 bead.</p> 
MATERIAL SPECIFICATIONS	
Material: LDPE	Color: White

<p>Additional Inspections</p> <p>Critical Dimension: Outer Diameter: 3.25 +/- .01 Part weight check. No flash allowed No contamination allowed. No silicone release spray allowed. No dirt, grease, or char particles on cap-seal. No warpage, or distortion, cap-seal must be flat. Cap-seal top surface must be smooth to allow hot stamping (if necessary)</p>	<p>Packaging Instructions</p>  <p>Individual Boxes Pieces Per Box:</p>
---	---

<p align="center"><u>DISCLAIMER</u></p> <p>THIS INFORMATION IS PROVIDED AS A GENERAL GUIDE, INCLUDING DIMENSIONS. IT IS THE CUSTOMER'S RESPONSIBILITIES TO SELECT THE PROPER CONTAINER FOR PRODUCT AND APPLICATION COMPATIBILITY.</p>	<p>DISTRIBUTED BY:</p> 	<p>REF NO.:</p> <p>DWG31177</p>
	<p>DESCRIPTION:</p> <p>2" White LDPE Plastic L-13W Sealing Overcap</p>	